Approved For Release 2002/10 CTA-RDP81B00879R001000070052-1

OLC-2723 Com n of 7 26 Hovember 1961

MEMORARDIM FOR THE RECORD

(Visits to West Coast Suppliers by	25X1A

2. A-12 Homefacturing Status

- a. First article final assembly is moving on schedule with no major problems.
- b. The left outer wing panel was delivered to final assembly on 16 Movember and will be fitted to aircraft on 22 Movember. The right outer panel will be completed in one week.
- c. One of the "A" ligs has already been moved to the new building. This building will have the same security as the present facility before any work starts.
- d. The ejector flags progrem is proceeding satisfactorily in the opinion of Lockbeed. The design procedure has always been to make them as light as possible and then test and beef up until they are o.k. Failures to date have not been of the catastrophic type nor will they hold up first flight.

	e. The	situation	bas been adequately
Demark .	up in the LAC men		which you have read.
The my	seent status shows	all but 15 of the	165 type required for the
first (urticle already on	hend and the remain	ning are due this week.

LL GEGLASSIFIED Approved For Release 2002/10/30 CTA-RDP8180087970010000780529067

DODUMENT NO. THE CHARGE IN CLASS.

25X1A

SECRET

-2-

Fittings will not hold up first flight but the future deliveries do not look too bright and I believe we should pursue this problem further.

- f. With reference to the aircraft systems, status of each is as follows:
 - (1) Air conditioning and cabin supercharging is all set.
 - (2) Hydraulic system very close to finished.
 - (3) Fuel system has been reworked due to engine change and CG shift, and is all set.

25X1A

(4) The control system is still in development test. The simulator is at work on the autopilot, stability sugmentation, pilot response and aircraft dynamic characteristics. LAC claims to be ready to fly now but feels considerably more refinement could be done before first flight. In any event this system should not hold up the first flight.

(i. LAC has a new high speed milling cutter now running experimentally on a HydroTel which removes 10-15 cubic inches per minute of Beta titanium on slabbing or roughing operations. This compares with a present rate of 2 cubic inches per minute and should considerably reduce rough machining costs in the near future.

h. The left vertical fin has been fitted to aircraft and is o.k. The right fin is in assembly and satisfactory.

- i. The chines are complete on #3 fuselage. He plastic chines on #2 yet.
- j. The inlets are moving along slowly and should be on the aircraft by 15 to 20 December.
- k. The static test air frame is in the mating Jig and should be complete by early December. The static test Jigs, structures, loading Jacks, hydraulies, etc., are approximately 98% complete. They are scheduling start of static test for 1 January.
- l. The requirement for 2 degrees misslignment on the remote gested drive brought to my attention by has been investigated. While this is a conservative estimate, the combination of thermal growth, structural deflections, and "G" loads indicate that misslignment will approach this rigure. LAC will get with P & W on this immediately.

25X1A

SECRET

	25)	K1A
	3. E discussed Jetster operating costs with they are propering an estimate for us.	and 25X1A
·	4. No decision has been reached by Lockheed and the switch to full depth honeycomb for the vertical fins. that Kelly is stalling while designing a new fin cometrue LAC silicons-asbestos material, or at least he has little in going any further with	ted of
25X1A	5. After reviewing the lack of progress at F & V, the possibility of using J-75 engines in the #2 air frame (GLJ on vacation). I feel this may become necessary to get into the AR flight test as rapidly as possible. I LAC feels that they would hesitate to start right out with the #2 air frame and would much prefer to start with one a time (paired with a J-75) in the #1 air frame. A program this probably will push AR flight testing into next summer	with Ty in order in midhion in J-58's in engine at prem like
25X1A	6. The AR status has been reported by Nr. Kiefer summary of the Hovember 14 meeting at the site. The only then was reported by this morning that they the problem in the bridge-balance type system and a start serious testing.	change since bave whipped

MEN/AX

Matribution:

2 - AC/DFD